

New Building!

New Fixtures!

No Problems?



Are You Sure?



## These Photos Speak For Themselves

These shiny new fixtures may look durable but underneath lies a whole different story.

The rugged looking wall mount leads you to believe that the entire fixture is equally durable. But that is not the case as shown by the tearing of the very thin metal of the bell housing.

On a newly installed fixture, the level of corrosion and white powdery residue on the nipple and nut may indicate yet another significant problem.

And, what lies underneath the wall mount?



## Know What You Are Specifying

Lumenelle's product design team has over a half century of experience in designing products to meet tough environmental military standards such as MIL-810-D.

Lumenelle can put that experience to work for you and let you know what to expect...

- ❖ Before you specify them,
- ❖ Before they are purchased,
- ❖ Before they are installed,
- ❖ Before they fail.